

EXTRAIT



36213
x 9
c = 138



36417
x 14
c = 126



368
x 10
c = 115





369
x 16
cote 224



370
x 15
c = 120



371
x 8
c = 104



2500



134



86,40





376/8
x 9
c = 304



379
x 6
c = 48,60



380/3
x 3
c = 120



384
x 14
c = 120



385/6
x 5
c = 53,5



390
x 8
c 160





391/4
x 13
cote 325



395/7
x 15
32
c=1080

398
x 14
c=182

399/0
2
c=81





401/4
x 12
c = 150



405
x 8
168



41413

x 2

C 470





41416

x 7

C 929




419/0
XS
c = 66



421/4
x12
36
c = 432







453/4
x 11
23,50
c 2,58



PA 18/20
x 7
c 420






PA 21
x 4
c 29



PA 22
x 3
c 84



PA 24
x 6
c 456



18.9.57

PA 25
x 9
c 270



PA 26
x 9
c 180





PA 27
x 8
14
c 112








PA 29
x 9
8
c-72



PA 30
x 13
32
c-415




PA 31
x 10
17
c-170



PA 32
x 11
28
c-308



PA 34
x 6
18
c-108




PA 35
x 10
11/30
c. 112
115




PA 36
x 12
60
c. 112
240




PA 37
x 12
15
c. 192



PA 38/9
x 4
70
c. 342
308










PA 40/41
x 8
25
c=200



PA 43
x 2
c=78



93

268



910



PA 4819
x 3
c = 243



PA 53
x 3
c = 114





PA 5476
 x 10
 50
 c=500



PA 58
 20
 c=40



PA 59
 x 2
 c=40



PA 60
 x 2
 c=52



PA 61
 x 2
 12
 c=24